MTN. HI TRUCK & EQUIPMENT PO BOX 165 WALLA WALLA WA. 99362 O-509-529-1761 F-509-529-1957

Invoice

| Date | Invoice # | |
|-----------|-----------|--|
| 7/23/2021 | 24286 | |

Bill To

HARRY JOHNSON PLUMBING
605 FOSTER RD.
WALLA WALLA, WA 99362

Ship To

| P.O. Number | Terms | Ship | Via |
|-------------|---------------|-----------|-----|
| #96A | DUE UPON RECE | 7/23/2021 | |

| Quantity | Item Code | Description | Price Each | Amount |
|----------|--------------|---|------------|-----------|
| | | 1996 KENWORTH T-800 VIN:TJ688302 ODO:855,752 | | |
| 4 | Repair Parts | CHR47697 WHEEL SEAL | 55.95 | 223.80T |
| 4 | Repair Parts | STM 3303106 AXLE GASKET | 2.30 | 9.20T |
| 4 | Repair Parts | AS1132 SLACK ADJUSTER | 118.95 | 475.80T |
| 2 | | E1147C S-CAM RH | 42.86 | 85.72T |
| 2 | Repair Parts | E1148C S-CAM LH | 42.86 | 85.72T |
| 2 | Repair Parts | E3993B S-CAM BUSHING KIT | 12.73 | 25.46T |
| 1 | Freight | FREIGHT | 25.00 | 25.00T |
| 1 | Repair Parts | S84-1017-1 KIT-SEAT BELT LH | 197.89 | 197.89T |
| 1 | Repair Parts | TL15011 LICENSE PLATE LIGHT | 6.95 | 6.95T |
| 1 | Repair Parts | TL 94902-3 PIGTAIL | 2.05 | 2.05T |
| 1 | Repair Parts | TL 30200R3 RED CLEARANCE LIGHT | 3.36 | 3.36T |
| 1 | Repair Parts | H5062 HEADLIGHT-LOW BEAM | 10.60 | 10.60T |
| 1 | Repair Parts | K301-197 SWITCH-MARKER LIGHT | 66.66 | 66.66T |
| 1 | Repair Parts | VEL 091230 RELAY | 7.87 | 7.87T |
| 8 | 1 | 80W-90 GEAR OIL | 7.90 | 63.20T |
| 1 | Repair Parts | GREASE | 4.95 | 4.95T |
| 1 | Environmena | ENVIRONMENTAL FEE/SHOP SUPPLIES | 176.83 | 176.83T |
| 19.5 | Labor Wash't | HOURS LABOR | 115.00 | 2,242.50T |
| | | DIAGNOSED S-CAMS | | |
| | | DIAGNOSED SLACK ADJUSTERS | | |
| | | REMOVED A SLACK ADJUSTER | | |
| | | INSTALLED NEW S-CAMS IN VERY BACK AXLE | | |
| | | INSTALLED NEW SLACK ADJUSTERS | | |
| | | INSTALLED THE HUBS AND BRAKES | | |
| | | INSTALLED DRUMS AND TIRES BACK ON THE BACK AXLE | | |
| | | TOPPED OFF GEAR OIL | | |
| | | REMOVED THE TIRES ON LEFT FRONT DRIVE AXLE TO | | |
| | | REMOVE THE DRUM, HUB, & S-CAM OUT | | |

Phone #

509-529-1761 Fax #

Total

Payments/Credits

Balance Due

509-529-1957

MTN. HI TRUCK & EQUIPMENT PO BOX 165 WALLA WALLA WA. 99362

O-509-529-1761 F-509-529-1957

Invoice

| Date | Invoice # |
|-----------|-----------|
| 7/23/2021 | 24286 |

| | | <u>a^</u> |
|---|-------|-----------|
| Bill To | 0.162 | Ship To |
| HARRY JOHNSON PLUMBING 605 FOSTER RD. WALLA WALLA, WA 99362 | 000 | |
| | | |

| P.O. Number | Terms | Ship | Via |
|-------------|---------------|-----------|-----|
| #96A | DUE UPON RECE | 7/23/2021 | |

| Quantity | Item Code | Description | Price Each | Amount |
|----------|-----------|---|------------|--------|
| | | INSTALLED NEW S-CAM | | |
| | | INSTALLED NEW WHEEL SEAL | | |
| | | PUT HUB BACK ON | | |
| | | RE-INSTALLED BRAKES AND DRUM | | |
| | | PUT TIRES BACK ON | | |
| | | INSPECTED CHECKED GEAR | | |
| | | GREASED EVERYTHING | | |
| | | INSPECTED ALL LIGHTS | | |
| | | REPLACED A RIGHT REAR MARKER LIGHT | | |
| | | REPLACED A NEW LICENSE PLATE LIGHT | | |
| | | REPAIRED LEFT FRONT PARK LIGHT | | |
| | | REPAIRED THE RIGHT PARK LIGHT | | |
| | | INSTALLED A NEW SEAT BELT | | |
| | | TOP CAB LIGHTS WERE DIM-DISCOVERED THEY WERE HOOKED TO THE DASH LIGHTS- | | |
| | | FOUND THE WIRING AND WIRED CORRECTLY | | |
| | | REPLACED BAD SWITCH | | |
| | | REMOVED WHEELS ON RIGHT FRONT DRIVE | | |
| | | REMOVED HUBS AND BRAKES | | |
| | | REMOVED HODS AND BRAKES REMOVED S-CAMS | | |
| | | REMOVED SLACK ADJUSTER, SEAL, AND BUSHINGS | | |
| | | PUT HUB BACK ON WITH NEW WHEEL SEAL | | |
| | | RE-INSTALLED SEALS, BUSHINGS, AND SLACK ADJUSTER | 2 | |
| | | PUT WHEELS BACK ON | ` | |
| | | Sales Tax 8.9 % 2015 | 8.90% | 330.5 |
| | | | | 22010 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | _ | -4-1 | |

509-529-1957