MTN. HI TRUCK & EQUIPMENT PO BOX 165 WALLA WALLA WA. 99362 O-509-529-1761 F-509-529-1957

Invoice

Date	Invoice #	
7/21/2021	24221	

		~ <u>?</u> ``
Bill To	- AG2	Ship To
HARRY JOHNSON PLUMBING	Op.	
605 FOSTER RD.		
WALLA WALLA, WA 99362		
		l .

P.O. Number	Terms	Ship	Via
2000	DUE UPON RECE	7/14/2021	

Quantity	Item Code	Description	Price Each	Amount
		2000 KENWORTH T-800 VIN:862600 ODO:284,462		
1	Repair Parts	334-1795 ASSY TORSION BAR 20 1/2 X 54"	1,476.61	1,476.61T
8	Repair Parts	013-812-1 5/8"-11X4" BOLT	6.21	49.68T
8	1	070-207-2 5/8" FLAT WASHER	0.60	4.80T
8		067-203-1 5/8"-11 LOCK NUT	2.36	18.88T
1	Repair Parts	TL 19200Y3 AMBER MARKER LIGHT	5.51	5.51T
1	Repair Parts	TL 4742 TURN SIGNAL LIGHT	34.95	34.95T
1	Environmena		160.02	160.02T
14	Labor Wash't	HOURS LABOR	115.00	1,610.00T
		CHECKED FLUID LEVEL IN TRANSMISSION-ALL GOOD ADJUSTED BRAKES CHECKED FLUID LEVELS IN BOTH REAR ENDS-ALL GOOD REMOVED OLD TRAILING ARMS INSTALLED NEW TRAILING ARMS ADJUSTED CLUTCH LOOKED AT RIDE HEIGHT AND LOWERED TIGHTENED STEER AXLE U-BOLTS PERFORMED ANNUAL D.O.T. INSPECTION DISCOVERED DURING DOT THAT RIGHT TURN SIGNAL WAS OUT- REPAIRED WIRE AND HAD TO CHANGE LIGHT ASSY FOUND NO PARK LIGHT NO RIGHT REAR TAIL LIGHT ALSO FOUND TWO MARKER LIGHTS OUT FOUND ALL THE WIRING AND INSPECTED FOR REPAIRS REPAIRED DAMAGED WIRING UNDER BOX Sales Tax 8.9 % 2015	8.90%	299.08
			8.90%	

509-529-1957