

MTN. HI TRUCK & EQUIPMENT
PO BOX 165
WALLA WALLA WA. 99362
O-509-529-1761 F-509-529-1957

Invoice

Date	Invoice #
8/25/2022	26043

PAID
09/12/2022

Bill To
HARRY JOHNSON PLUMBING 605 FOSTER RD. WALLA WALLA, WA 99362

Ship To

P.O. Number	Terms	Ship	Via
90A	DUE UPON RECE...	8/25/2022	

Quantity	Item Code	Description	Price Each	Amount
		1990 KW T00, SERIAL NO LM542293,ENGINE NO 11555071, ODOMETER 1,090,997 LICENSE A50578N REPAIR TRANSMISSION		
1	Repair Parts ...	FUL 18135 SNAP RING	1.30	1.30T
1	Repair Parts ...	13T38541 GASKET	12.25	12.25T
2	Repair Parts ...	FUL 16723 SNAP RING	0.93	1.86T
1	Repair Parts ...	FUL A3697 KEY & PIN ASSY	30.94	30.94T
1	Repair Parts ...	FUL 15932 WASHER	24.47	24.47T
1	Repair Parts ...	FUL 20388E GEAR, MAIN SHAFT	174.43	174.43T
1	Repair Parts ...	FUL 4303859E COUPLER, MAIN SHAFT	49.66	49.66T
1	Repair Parts ...	FUL 14291 SNAP RING	1.10	1.10T
1	Repair Parts ...	FUL 22254 HEX FLANGE NUT	18.44	18.44T
1	Repair Parts ...	FUL K1603 GASKET KIT, 13 SPEED	21.33	21.33T
1	Repair Parts ...	FUL K2002 O-RING KIT	18.64	18.64T
1	Repair Parts ...	FUL K1447 O-RING KIT	16.87	16.87T
1	Repair Parts ...	ABI K3494AB SYNCHRONIZER KIT	253.94	253.94T
1	Repair Parts ...	FUL 81057 BALL BEARING	75.83	75.83T
1	Repair Parts ...	1091691 SEAL	31.60	31.60T
15	Repair Parts ...	QTS 50W TRANSMISSION OIL	14.49	217.35T
25	Labor Wash't...	HOURS LABOR	135.00	3,375.00T
1	Environmena...	ENVIRONMENTAL FEE/SHOP SUPPLIES	129.75	129.75T
		TOOK OUT AIR TANK ON LEFT SIDE OF FRAME		
		TOOK OFF DRIVE LINE		
		REMOVED AIR LINES AND WIRING		
		REMOVED BACK OF TRANSMISSION		
		REPLACED B ACK OF TRANSMISSION		
		REPLACED DRIVELINE		
		REPLACED AIR TANK		
		REPLACED AIR LINES AND WIRING		
		Sales Tax 8.9 % 2015	8.90%	396.47

Total	\$4,851.23
--------------	------------

Payments/Credits	-\$4,851.23
Balance Due	\$0.00

Phone #	
509-529-1761	Fax #
	509-529-1957